



Shadow Log[®] Guarantees Trip Data

Plug-and-Play Logger, Ideal for Export Shipments

Shadow Log[®] is a patented failsafe feature that sets the FlashLink Mini PDF In-Transit Logger apart from other brands. It ensures temperature data is recorded even if a shipper fails to start the unit, and receivers will always have a trip report when a load arrives. This compact, single-use logger incorporates a USB connector and on-board software, making it quick and easy to download trip history without special reading devices or installing software. PDF reports are automatically generated when the logger is plugged into the USB port of a PC, tablet, or printer, where they can be saved and shared by email.

- Shadow Log[®] guarantees trip data
- One PDF report with °F and °C readings
- 10 minute sample rate
- One model for any trip duration, up to 85 days
- Recorded data automatically scales to a full graph
- Measurement range -22°F to 158°F (-30°C to 70°C)

FlashLink Mini PDF Logger

SHIPPER INSTRUCTIONS

- Fill out the white shipping label located below the logger.
- Press and hold the green START button until the green ACTIVE LED flashes 6 times.
- Activated logger flashes green every 12 seconds.
- Remove barcode label from card, apply to shipping document. Serial number on barcode matches PDF trip report for traceability.
- Use adhesive strips on back of card to place logger on top of pallet or package, or insert card into plastic packing envelope and attach to pallet.

INSTRUCCIONES DEL ENVIADOR

- Llene la etiqueta blanca de envío que se encuentra debajo del registrador.
- Mantenga presionado el botón verde START hasta que el LED verde ACTIVE parpadee 6 veces.
- El registrador activado parpadeará en verde cada 12 segundos.
- Retire las etiquetas adhesivas del código de barras, aplique al papelado. Número de serie en el código de barras es consistente con el informe PDF para la trazabilidad.
- Utilice las tiras adhesivas para colocar el registrador en la parte superior de la paleta o paquete, o inserte la tarjeta en el sobre de plástico y agréguela en la paleta.

RECEIVER INSTRUCTIONS

CAUTION: If the green ACTIVE light is not flashing, the logger is in Shadow Log[®] mode (fail safe data logging). Do not push the START button. Follow steps 1 and 2 to recover Shadow Log data. If the logger is active the green ACTIVE light will be flashing. If there has been a temperature excursion, the red ALARM light will be flashing.

- Remove logger from card.
- Plug into USB port of computer and a window will automatically open to access the PDF Report.

INSTRUCCIONES DEL RECIPIENTE

PRECAUCIÓN: Si la luz verde ACTIVE no está parpadearando, el registrador está en el modo Shadow Log[®] (registro de datos a prueba de fallos). No presione el botón START. Siga los pasos 1 y 2 para recuperar los datos de Shadow Log. Si el registrador está activo, la luz verde ACTIVE parpadearará. Si ha habido una excursión de temperatura, la luz roja de ALARM parpadearará.

- Retire el registrador de la tarjeta.
- Conecte al puerto USB en la computadora para generar automáticamente un archivo PDF.

MODEL 31010 °F/°C
DELAY START: 30 MIN
SAMPLE RATE: 10 MIN
GMT/UTC: 0

www.deltatrak.com

